



PRODUCT BULLETIN

Date: 9/4/2024

Product: **XL 866**

Product Code: 171901

We have recently discovered that the propellant in the XL 866 is not performing as expected, resulting in the product being dispensed in a stringy, inconsistent manner.

As a temporary solution, we are offering our **Aerosol Chain & Cable Lube** at the same price as the XL 866. This product provides similar benefits and is a suitable alternative while we wait on the arrival of our new shipment of XL 866.

We have also adjusted the inventory code for **Aerosol Chain & Cable Lube** to match that of XL 866. If you would like to substitute any backorders for XL 866 with Chain & Cable Lube, please reach out to Sales Support.

We will send out a new update as soon as we have a ship date for XL 866. Also if your customer has XL 866 on their shelves that is spraying out in a stringy-like manner please contact purchasing for a replacement.