# Orange Away #1646

# **Aerosol All Natural Solvent Cleaner**



### Features:

- All natural and biodegradable
- Uses no petroleum distillates
- 95% d-limonene, which is a powerful solvent made from orange peel extracts
- Leaves behind a fresh, orange scent as it cleans
- Contains the power and versatility of a solvent cleaner with the convenience and ease of an aerosol
- Strong enough to remove tar, grease grime, wax, gum deposits, adhesives and more
- Removes heavy-duty buildup
- VOC compliant

## **Description:**

ORANGE AWAY is a powerful, natural cleaner that is strong enough to strip away tar, wax, gum deposits, adhesives and more. It is made with the solvent d-Limonene, which is made from natural orange peel extracts. It combines the power and versatility of a multipurpose solvent cleaner, with the ease of an aerosol.

## **Effective Against:**

- Tar and Asphalt Deposits
- Odors
- Printing Ink
- Grease

- Gum and Wax Deposits
- Decals
- Carbon Deposits
- Grime

# **Applications:**

Tire Marks

- Construction Equipment Cleaner
- Tool Degreaser
- Engine Degreaser
- Carpet Spot Cleaner
- Mastic Adhesive Remover

# PROCHEM ORANGE AWAY EMULSIFIABLE ORGANIC SOLVENT ALL-NATURAL d-LIMONENE NEP OUT OF REACH OF CHILDREN WARNING RAMMABIE MAY GLUES EYE BRITATION. GONIENIS UNDER PRESSURE. IN CONTROL OF CHILDREN WARNING NATION OF CHILDREN WARNING NATION

# **Product Characteristics:**

Appearance:		Aerosol.
Odor:		Citrus scent.
Vapor Pressure:		30 – 45 psig @ 70°F (estimated).
Specific Gravity:		0.7583 g/ml (estimated).
Solubility:		No data available.
Flash Point:		-156°F propellant (estimated).
VOC:		>90%
Viscosity, kinematic: <2		<20 cSt
Storage:	Stor	re locked up. Protect from sunlight.
	Do r	not expose to temperatures
	exce	eeding 50°F/122°F.
Transport Information:		
Proper Shipping Name:		e: Aerosols flammable, (each not
		exceeding 1 L capacity).
UN Number:		UN1950
Class:		2.1
	Odor: Vapor Pressure: Specific Gravity: Solubility: Flash Point: VOC: Viscosity, kinema Storage:  Transport Inform Proper Shipping UN Number:	Odor:  Vapor Pressure:  Specific Gravity:  Solubility:  Flash Point:  VOC:  Viscosity, kinematic:  Storage:  Storage:  Transport Informatio  Proper Shipping Name  UN Number:

## **Directions:**

Spray directly onto surface. Allow to work for 30 seconds. Flush away loosened deposits with water. On fabrics and plastics, test in an inconspicuous area before using.

## Pictograms:







Signal Word: DANGER

**Personal Protective Equipment Required:** 







## **DOT Hazard Label:**

